


Punteras aisladas de punta hueca – SISTEMA W



Materiales














Poliamida 6.6 norma DIN 46228/4.

Certificados y normas aplicables



Temperatura de trabajo

-40°C a 105°C.

Referencia	Color	Sección mm ²	L mm	Embalaje unidades
W-0,25		0,25	8	500
W-0,50		0,50	8	500
W-0,50-L			10	500
W-0,75		0,75	8	500
W-0,75-L			12	500
W-1		1,00	8	500
W-1-L			12	500
W-1,50		1,50	8	500
W-1,50-L			18	500
W-2,50		2,50	8	500
W-2,50-L			18	500
W-4		4,00	10	200
W-4-L			18	200
W-6		6,00	12	100
W-6-L			18	100
W-10		10,00	12	100
W-10-L			18	100
W-16		16,00	12	100
W-16-L			18	100
W-25		25,00	16	100
W-25-L			22	100
W-35		35,00	16	100
W-35-L			22	100
W-50		50,00	20	100
W-50-L			22	100